

**PROFORMA REGARDING SAFE DRINKING WATER AND
SANITARY CONDITION CERTIFICATE**

No. 643 // Date: 25.09.2025

It is certified that an inspection team headed by Junior Engineer-I, RWS&S Section, Karanjia (Name of Officers with designation) from Office of the Junior Engineer, RWS&S Section, Karanjia (PR&DW Department) (Name of Department /Office) inspected the Odisha Adarsha Vidyalaya (OAV) at Badadeuli, Karanjia (Name address of the school) on 23.09.2025 and found that the Odisha Adarsha Vidyalaya, Badadeuli (Name of School) has safe drinking water facilities for the students and members of the staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as the norms prescribed by the Central/State/U.T Govt.

The above valid for the period of (One Year)

Signature with seal :

Name

Designation

pm
25/9/25

Manoj Kumar Das
Asst. Executive Engineer
R.W.S. & S. Sub-Division,
Karanjia

To

The Principal,
OAV, Badadeuli, Karanjia.


SUB-DIVISIONAL WATER TESTING LABORATORY RWS&S SUB-DIVISION, KARANJIA

Location of the source : *Near OAV Primises, Badadeuli, Karanja.*
Sample received Date. : *19.09.2025*
Sample testing Date. : *22.09.2025*

Water Quality Test Report for the source of Odisha Adarsha Vidyalaya, Badadeuli under Karanja Block.

Sl no	Parameters	Desivable Limit by BIS	Permissible Limit by BIS	Actual Value
1	Hardness	200 mg/l	600 mg/l	68 Mg/l
2	Chloride	250 mg/l	1000 mg/l	32 Mg/l
3	Flouride	1.0 mg/l	1.5 mg/l	0.21 Mg/l
4	Iron	0.1 mg/l	1.0 mg/l	0.22 Mg/l
5	Alkalinity	200 mg/l	600 mg/l	56 Mg/l
6	TDS	500 mg/l	2000 mg/l	80..3 Mg/l
7	pH	6.5	8.5	7.41
8	Turbidity	1.0 NTU	5.0 NTU	0.25 NTU

Note - As per above parameters tested water is safe range.


22/09/2025
Lab chemist
RWS&S Sub division
Karanja.